


HOLE IN P.C.B $\phi 4.0$
P.C.B THICKNESS 1.2~1.7



HOLE IN CHASSIS $\phi 5.5$
CHASSIS THICKNESS 1.2~1.8

PART NO.	A
-RBS-5	5
-RBS-6	6
-RBS-7	7
-RBS-8	8
-RBS-10	10
-RBS-12	12
-RBS-14	14
-RBS-18	18
-RBS-20	20