




Model	Shank Dia (D)	Cutter Dia (d)	Cutter Length (L1)	Total Length (L)
3.175*1.0*3*38	3.175	1	3	38
3.175*1.5*6*38	3.175	1.5	6	38
3.175*1.5*8*38	3.175	1.5	8	38
3.175*1.5*12*38	3.175	1.5	12	38
3.175*2.0*8*38	3.175	2	8	38
3.175*2.0*12*38	3.175	2	12	38
3.175*2.0*17*38	3.175	2	17	38
3.175*2.0*22*45	3.175	2	22	45
3.175*2.5*10*38	3.175	2.5	10	38
3.175*2.5*12*38	3.175	2.5	12	38
3.175*2.5*17*38	3.175	2.5	17	38
3.175*2.5*22*45	3.175	2.5	22	45
3.175*12*38	3.175	3.175	12	38
3.175*15*38	3.175	3.175	15	38
3.175*17*38	3.175	3.175	17	38
3.175*22*45	3.175	3.175	22	45
3.175*25*45	3.175	3.175	25	45
3.175*28*50	3.175	3.175	28	50
3.175*32*55	3.175	3.175	32	55
4*12*45	4	4	12	45
4*17*45	4	4	17	45

4*22*45	4	4	22	45
4*25*50	4	4	25	50
4*28*55	4	4	28	55
4*32*60	4	4	32	60
5*22*45	5	5	22	45
6*17*45	6	6	17	45
6*22*45	6	6	22	45
6*25*50	6	6	25	50
6*28*55	6	6	28	55
6*32*60	6	6	32	60
6*35*65	6	6	35	65
6*42*70	6	6	42	70
6*52*80	6	6	52	80
6.35*22*50	6.35	6.35	22	50
8*22*50	8	8	22	50
8*32*60	8	8	32	60
10*22*60	10	10	22	60
10*32*70	10	10	32	70
12*22*60	12	12	22	60
12*32*70	12	12	32	70



25 degree Helix angle,
efficiency is not generally fast